


بسم الله الرحمن الرحيم
تمرين ترسن:

طراحی اجزای I

جله ۱۶



$$\sigma_{max} = K_t \cdot \varepsilon_0$$

ضریب ترنس

$$\gamma_{max} = K_{ts} \cdot \gamma_0$$

با استفاده از جداول آخرباب ماتلاب رسانیده اس.

احدار بارگذار اس نوسانی عامل رلهای تردی دخل می شود.

$$\sigma_{max} = K_f \cdot \varepsilon_0$$

ضریب ترنس در بارگذار اس نوسانی

$$K_f = 1 + q(K_t - 1)$$



$$\frac{q}{K_t - 1} = \frac{K_f - 1}{K_f}$$

ضریب ترنس
حرایت ها

$$q_{\text{shear}} = \frac{k_{fs} - 1}{k_{ts} - 1} \rightarrow k_{fs} = 1 + q_{\text{shear}} (k_{ts} - 1)$$


بارگذاری نزدیکی $\tau_{\max} = k_{fs} \tau_0$

(Table 6-20, 21) مربوطه حالت ماده: سرمه



(Copyright © The McGraw-Hill Companies, Inc. Permission required for reproduction or display.)

Notch radius r , mm



(Copyright © The McGraw-Hill Companies, Inc. Permission required for reproduction or display.)






Table A-13Charts of Theoretical Stress-Concentration Factors K_t^* **Figure A-13-1**

Bar in tension or simple compression with a transverse hole: $\sigma_0 = F/A$, where $A = (w - d)t$ and t is the thickness.

**Figure A-13-2**

Rectangular bar with a transverse hole in bending. $\sigma_0 = Mc/I$, where $I = (w - d)h^3/12$.

**Figure A-13-3**

Notched rectangular bar in tension or simple compression. $\sigma_0 = F/A$, where $A = dt$ and t is the thickness.




Table A-13Charts of Theoretical Stress-Concentration Factors K_t^* (Continued)**Figure A-13-4**

Notched rectangular bar in bending. $\sigma_0 = Mc/l$, where $c = d/2$, $l = td^3/12$, and t is the thickness.






Figure A-13-11

Figure A-13-5

Rectangular filleted bar in tension or simple compression. $\sigma_0 = F/A$, where $A = dt$ and t is the thickness.

**Figure A-13-6**


Rectangular filleted bar in bending. $\sigma_0 = Mc/l$, where $c = d/2$, $l = td^3/12$, t is the thickness.




*Factors from R. E. Peterson, "Design Factors for Stress Concentration," Machine Design, vol. 23, no. 2, February 1951, p. 169; no. 3, March 1951, p. 161, no. 5, May 1951, p. 159; 1951, p. 172; no. 7, July 1951, p. 155. Reprinted with permission from Machine Design, a Penton Media Inc. publication.

Table A-13Charts of Theoretical Stress-Concentration Factors K_t^* (Continued)**Figure A-13-7**

Round shaft with shoulder fillet in tension. $\sigma_0 = F/A$, where $A = \pi d^2/4$.

**Figure A-13-8**

Round shaft with shoulder fillet in torsion. $\tau_0 = Tc/J$, where $c = d/2$ and $J = \pi d^4/32$.

**Figure A-13-9**

Round shaft with shoulder fillet in bending. $\sigma_0 = Mc/l$, where $c = d/2$ and $l = \pi d^4/64$.




Table A-13Charts of Theoretical Stress-Concentration Factors K_t^* (Continued)**Figure A-13-10**

Round shaft in torsion with transverse hole.

Bending and/or tension

and/or shear

Source: W. D. Pilkey, Peterson's

Stress Concentration Factors,

2nd ed., John Wiley & Sons,

New York, 1997, p. 115.

Figure A-13-11

Round shaft in bending with a transverse hole. $\sigma_0 = M/[(\pi D^3/32) - (dD^2/6)]$, approximately.




**Figure A-13-12**

Plate loaded in tension by a pin through a hole. $\sigma_0 = F/A$, where $A = (w - d)t$. When clearance exists, increase K_t 35 to 50 percent. [M. M. Frocht and H. N. Hill, "Stress Concentration Factors around a Central Circular Hole in a Plate Loaded through a Pin in Hole," J. Appl. Mechanics, vol. 7, no. 1, March 1940, p. A-5.]




(contin)


*Factors from R. E. Peterson, "Design Factors for Stress Concentration," Machine Design, vol. 23, no. 2, February 1951, p. 169; no. 3, March 1951, p. 161, no. 5, May 1951, p. 159; no. 6, June 1951, p. 173; no. 7, July 1951, p. 155. Reprinted with permission from Machine Design, a Penton Media Inc. publication.

Table A-13Charts of Theoretical Stress-Concentration Factors K_t^* (Continued)**Figure A-13-13**


Grooved round bar in tension.
 $\sigma_0 = F/A$, where
 $A = \pi d^2/4$.

**Figure A-13-14**

Grooved round bar in bending.
 $\sigma_0 = Mc/l$, where
 $c = d/2$ and $l = \pi d^4/64$.

**Figure A-13-15**

Grooved round bar in torsion.
 $\tau_0 = Tc/J$, where $c = d/2$
and $J = \pi d^4/32$.



*Factors from R. E. Peterson, "Design Factors for Stress Concentration," Machine Design, vol. 23, no. 2, February 1951, p. 169; no. 3, March 1951, p. 161, no. 5, May 1951, p. 159; no. 6, June 1951, p. 173; no. 7, July 1951, p. 155. Reprinted with permission from Machine Design, a Penton Media Inc. publication.

Table A-13Charts of Theoretical Stress-Concentration Factors K_t^* (Continued)**Figure A-13-16**

Round shaft with flat-bottom groove in bending and/or tension.

$$\sigma_0 = \frac{4P}{\pi d^2} + \frac{32M}{\pi d^3}$$

Source: W. D. Pilkey, Peterson's Stress Concentration Factors, 2nd ed. John Wiley & Sons, New York, 1997, p. 115




Table A-13Charts of Theoretical Stress-Concentration Factors K_t^* (Continued)

Figure A-13-13

Figure A-13-17

Round shaft with flat-bottom groove in torsion.

$$\tau_0 = \frac{16T}{\pi d^3}$$

Source: W. D. Pilkey, *Peterson's Stress Concentration Factors*, 2nd ed. John Wiley & Sons, New York, 1997, p. 133




Figure A-13-14

Generalized chart for
torsion of a shaft with
a flat-bottomed groove.

Figure A-13-15

Generalized chart for
 $r = 0.1d$, $d = 0.75D$,
 $a = 0.25D$.