



بِسْمِ اللّٰهِ الرَّحْمٰنِ الرَّحِیْمِ

مُرَاوِیْیَ

حَلَبَ ۱۳



تمرکز تنش:



$$\sigma_{max} = K_t \cdot \sigma_0$$

ضریب تمرکز تنش

$$\tau_{max} = K_{ts} \cdot \tau_0$$

K_t با استفاده از جداول آخر کتاب قابل دستیابی است.

اما در بارگذاری نوسانی عامل دیگری نیز دخیل می شود.

$$\sigma_{max} = K_f \cdot \sigma_0$$

در بارگذاری نوسانی

ضریب تمرکز تنش در بارگذاری نوسانی

$$K_f = 1 + q(K_t - 1)$$

$$q = \frac{K_f - 1}{K_t - 1}$$

ضریب حساسیت ماده
در شدت ترک

$$q_{\text{shear}} = \frac{K_{fs} - 1}{K_{ts} - 1} \rightarrow K_{fs} = 1 + q_{\text{shear}} (K_{ts} - 1)$$

با رکنه در این نوعی $\tau_{\text{max}} = K_{fs} \tau_0$

q: ضریب حالت ماده بر رنده ترک (Table 6-20, 21)

$$q = \frac{1}{1 + \frac{\sqrt{a}}{\sqrt{r}}}$$

\sqrt{a} : Neuber constant
خواص ماده



$$\sqrt{a} = 0.246 - 3.08(10^{-3}) S_{ut} + 1.51(10^{-5}) S_{ut}^2 - 2.67(10^{-8}) S_{ut}^3$$

Bending or axial

$$\sqrt{a} = 0.190 - 2.51(10^{-3}) S_{ut} + 1.35(10^{-5}) S_{ut}^2 - 2.67(10^{-8}) S_{ut}^3$$

Torsion

(Copyright © The McGraw-Hill Companies, Inc. Permission required for reproduction or display.)



$$q = \frac{1}{1 + \frac{\sqrt{a}}{\sqrt{r}}}$$

\sqrt{a} : Neuber constant
خواص با دو

$$\sqrt{a} = 0.246 - 3.08(10^{-3})S_{ut} + 1.51(10^{-5})S_{ut}^2 - 2.67(10^{-8})S_{ut}^3$$

$$\sqrt{a} = 0.190 - 2.51(10^{-3})S_{ut} + 1.35(10^{-5})S_{ut}^2 - 2.67(10^{-8})S_{ut}^3$$

Bending or axial

Torsion

(Copyright © The McGraw-Hill Companies, Inc. Permission required for reproduction or display.)




Table A-13

Charts of Theoretical Stress-Concentration Factors K_t^*

Figure A-13-1

Bar in tension or simple compression with a transverse hole. $\sigma_0 = F/A$, where $A = (w - d)t$ and t is the thickness.




Figure A-13-2

Rectangular bar with a transverse hole in bending. $\sigma_0 = Mc/I$, where $I = (w - d)h^3/12$.




Figure A-13-3

Notched rectangular bar in tension or simple compression. $\sigma_0 = F/A$, where $A = dt$ and t is the thickness.




Table A-13

Charts of Theoretical Stress-Concentration Factors K_t^* (Continued)

Figure A-13-4

Notched rectangular bar in bending. $\sigma_0 = Mc/I$, where $c = d/2$, $I = td^3/12$, and t is the thickness.




Figure A-13-5

Rectangular filleted bar in tension or simple compression. $\sigma_0 = F/A$, where $A = dt$ and t is the thickness.





Figure A-13-6


Rectangular filleted bar in bending. $\sigma_0 = Mc/I$, where $c = d/2$, $I = td^3/12$, t is the thickness.




*Factors from R. E. Peterson, "Design Factors for Stress Concentration," Machine Design, vol. 23, no. 2, February 1951, p. 169; no. 3, March 1951, p. 161, no. 5, May 1951, p. 159; 1951, p. 173; no. 7, July 1951, p. 155. Reprinted with permission from Machine Design, a Penton Media Inc. publication.

Table A-13Charts of Theoretical Stress-Concentration Factors K_t^* (Continued)**Figure A-13-7**

Round shaft with shoulder fillet
in tension. $\sigma_0 = F/A$, where
 $A = \pi d^2/4$.

**Figure A-13-8**

Round shaft with shoulder fillet
in torsion. $\tau_0 = T_c/J$, where
 $c = d/2$ and $J = \pi d^4/32$.

**Figure A-13-9**

Round shaft with shoulder fillet
in bending. $\sigma_0 = Mc/I$, where
 $c = d/2$ and $I = \pi d^4/64$.




Figure A-13-10

Round shaft in torsion with transverse hole.




Figure A-13-11

Round shaft in bending with a transverse hole. $\sigma_0 = M/[(\pi D^3/32) - (dD^2/6)]$, approximately.





Figure A-13-12

Plate loaded in tension by a pin through a hole. $\sigma_0 = F/A$, where $A = (w - d)t$. When clearance exists, increase K_t 35 to 50 percent. (M. M. Frocht and H. N. Hill, "Stress Concentration Factors around a Central Circular Hole in a Plate Loaded through a Pin in Hole," *J. Appl. Mechanics*, vol. 7, no. 1, March 1940, p. A-5.)



(contin)

Table A-13

Charts of Theoretical Stress-Concentration Factors K_t^* (Continued)

Figure A-13-13

Grooved round bar in tension.

$\sigma_0 = F/A$, where
 $A = \pi d^2/4$.




Figure A-13-14

Grooved round bar in bending. $\sigma_0 = Mc/I$, where
 $c = d/2$ and $I = \pi d^4/64$.





Figure A-13-15

Grooved round bar in torsion.

$\tau_0 = Tc/J$, where $c = d/2$
 and $J = \pi d^4/32$.



*Factors from R. E. Peterson, "Design Factors for Stress Concentration," Machine Design, vol. 23, no. 2, February 1951, p. 169; no. 3, March 1951, p. 161, no. 5, May 1951, p. 159; no. 6, June 1951, p. 173; no. 7, July 1951, p. 155. Reprinted with permission from Machine Design, a Penton Media Inc. publication.


Table A-13

Charts of Theoretical Stress-Concentration Factors K_t^* (Continued)

Figure A-13-16
 Round shaft with flat-bottom groove in bending and/or tension.

$$\sigma_0 = \frac{4P}{\pi d^2} + \frac{32M}{\pi d^3}$$

Source: W. D. Pilkey, *Peterson's Stress Concentration Factors*, 2nd ed. John Wiley & Sons, New York, 1997, p. 115



0.5	0.6	0.7	0.8	0.9	1.0	2.0	3.0	4.0	5.0	6.0
0.25	0.67	2.42	0.64	2.18	0.61	2.00	0.58	1.97	0.54	1.94
0.275	0.65	2.48	0.61	2.16	0.58	1.97	0.55	1.94	0.51	1.91
0.30	0.64	2.52	0.58	2.14	0.54	1.94	0.52	1.91	0.48	1.88

Table A-13Charts of Theoretical Stress-Concentration Factors K_t^* (Continued)**Figure A-13-17**

Round shaft with flat-bottom groove in torsion.

$$\tau_0 = \frac{16T}{\pi d^3}$$

Source: W. D. Pilkey, *Peterson's Stress Concentration Factors*, 2nd ed. John Wiley & Sons, New York, 1997, p. 133

